Pinetop-Studios - PSS #10

Shower heads - CLR - Clear Blockage

12/21/2021 05:52 AM - Sieu Ngo

Status:NewStart date:12/21/2021Priority:Med-HighDue date:Assignee:% Done:0%Category:Estimated time:0.00 hour

Description

This needs to be done every two yrs - or upon visual inspection.

We have extra shower heads - put in replacement, soak the old unit until clean.

Most of the heads were done early November ... need a run thru of all units - in particular, rooms were were unable to access previously (such as 122).

During cleaning service, any head found to have blockage, leave comments on this ticket.

12/06/2025 1/1